

# TIMBER SUPERSTRUCTURES

3/7/2024

IL NBI Refresher Course 2024

1

## Item 59 - Timber Superstructures

### Common Timber Superstructure Types:

- Solid sawn multi-beam bridges
- Glulam multi-beam bridges
- Trusses and covered bridges



3/7/2024

I-2

2

## Item 59 - Timber Superstructures

### Solid Sawn Lumber Beams

- This type of bridge has been around for thousands of years!
- Primary members consist of solid sawn or hewn timber
- Short spans on timber or masonry substructures
- Rarely used for vehicle bridges now



I-3

3/7/2024

3

## Item 59 - Timber Superstructures

### Glulam Beams

- This type of structure has been around since the 1970's
- Provides greater strength and allows longer spans
- High costs limits use



I-4

3/7/2024

4

## Item 59 - Timber Superstructures

### Truss / Arch / Covered

- Have been in use since at least the 1500's
- Primary members can consist of sawn timber or glulam
- Allows for longer spans
- High costs limits use



I-5


3/7/2024

5


## Item 59 - Timber Superstructures

### Timber Damage - Checks

- A separation of the wood fibers across or along the growth rings
- It does **not** extend completely thru the member
- Caused by the timber fibers drying/shrinking at different rates in the cross section
- Checking typically does not have a significant affect on beam capacity
- Severe checking should be documented



Sketch of Checks



Pictures from Montana DOT Timber Bridge Inspection Guide

I-6

3/7/2024


6

## Item 59 - Timber Superstructures

### Timber Damage - Shakes

- A separation or plane of weakness between growth rings usually caused by events before the wood is milled
- Shakes typically do not have a significant affect on beam capacity
- Severe, deep or long shakes should be documented

Pictures from Montana DOT Timber Bridge Inspection Guide



Sketch of Shakes



I-7

3/7/2024


7

## Item 59 - Timber Superstructures

### Timber Damage - Splits

- A check that extends completely thru a member
- It does not propagate thru the top or bottom of the member
- Often caused by seasoning of the wood
- Minor splits typically do not significantly affect the beam capacity of the member (< 20% of member length)

Pictures from Montana DOT Timber Bridge Inspection Guide



Sketch of a Split



I-8

3/7/2024

8

## Item 59 - Timber Superstructures

### Timber Damage - Cracks

- A crack extends completely thru a member, typically starting in the tension portion and extending at an angle away from the tension face
- Often starts in high stress area at a stress riser such as a knot, impact damage or where a check follows the grain to the tension face surface
- Cracks affect the bending capacity of the beam & often lead to breaks
- Repair often required



Sketch of a Crack



Moderate Crack



Severe Crack

Pictures from Montana DOT Timber Bridge Inspection Guide

I-9


3/7/2024

9

## Item 59 - Timber Superstructures

### Timber Damage - Breaks

- Two Types: **Partial** & Complete
- Partial – loss of all strength in a portion of the member's cross section. Important to note the portion of the member that is still intact.
- Significantly reduces beam capacity – repair or replacement required



Sketch of a Partial Break



Pictures from Montana DOT Timber Bridge Inspection Guide

I-10

3/7/2024


10



## Item 59 - Timber Superstructures

### Timber Damage - Breaks

- Two Types: Partial & **Complete**
- Complete – loss of all strength of a member, extends across the entire member
- Loss of beam capacity – repair or replacement required



Sketch of a Complete Break



Pictures from Montana DOT Timber Bridge Inspection Guide

I-11

3/7/2024

11

## Item 59 - Timber Superstructures

### Timber Damage – Decay & Crushing

- Deterioration typically caused by fungus, mold, bacteria & sunlight
- Causes loss of strength of member & often leads to crushing in compression areas
- Can be detected visually (external) or by sounding (internal)
- Determine and record extent of rot in member cross section when found



Pictures from Montana DOT Timber Bridge Inspection Guide

I-12

3/7/2024

12

## Item 59 - Timber Superstructures

### Key Indicators

- Cracks
- Decay
- Splitting
- Crushing
- Fire damage

Code	Description
8	VERY GOOD. May have only <b>very minor defects</b> in beams or stringers at <b>non-critical locations</b> .
7	GOOD. Minor <b>insignificant decay, cracking, or splitting</b> of beams or stringers.
6	SATISFACTORY. <b>Some decay, cracking, or splitting</b> of beams or stringers may be occurring near the main load carrying portions. <b>Fire damage limited to</b> surface scorching with no significant section loss.
5	FAIR. <b>Moderate decay</b> up to 10%, cracking, or splitting of beams or stringers but <b>no significant effect in critical areas</b> such as beam ends and mid-span. <b>Fire damage limited to</b> surface charring with minor section loss up to 10%.

I-13

3/7/2024

13

## Item 59 - Timber Superstructures

### Key Indicators

- Cracks
- Decay
- Splitting
- Crushing
- Fire damage

Code	Description
4	POOR. <b>Extensive decay, cracking, splitting or crushing</b> of beams or stringers, or <b>fire damage with</b> main load carrying portions affected. Section loss up to 30%.
3	SERIOUS. <b>Severe decay, cracking, splitting or crushing</b> of beams or stringers, or <b>fire damage with</b> major section loss up to 50% in critical load carrying portions of members. A <b>further progression of problems</b> noted for a condition rating of "4".
2	CRITICAL. <b>Beam ends may be crushed or split with settlement of deck. Any further deterioration of problems noted for a condition rating of "3"</b> . Section loss over 50%, special feature inspection is required to allow bridge to remain open. The Bureau of Bridges and Structures shall be notified immediately.

I-14

3/7/2024

14

## Item 59 - Timber Superstructures

### Very Good Condition

- Timber super and deck
- No significant defects noted
- Not the 1<sup>st</sup> inspection



**VERY GOOD.** May have only **very minor defects** in beams or stringers at non-critical locations.

I-15

3/7/2024

15

## Item 59 - Timber Superstructures

### Good Condition

- Sawn timber super and deck
- Minor checks in timber beams
- No section loss



**GOOD.** **Minor** insignificant decay, **cracking**, or splitting of beams or stringers.

I-16

3/7/2024

16



## Item 59 - Timber Superstructures

### Satisfactory Condition

- ❑ Sawn timber super and deck
- ❑ Some moderate splitting & checking
- ❑ Minor decay



**SATISFACTORY.** Some decay, cracking, or splitting of beams or stringers may be occurring near the main load carrying portions. Fire damage limited to surface scorching with no significant section loss.

I-17


3/7/2024

17

## Item 59 - Timber Superstructures

### Fair Condition

- ❑ Sawn timber super and deck
- ❑ Minor checks
- ❑ Moderate decay with 10% section loss



**FAIR.** Moderate decay up to 10%, cracking, or splitting of beams or stringers but no significant effect in critical areas such as beam ends and mid-span. Fire damage limited to surface charring with minor section loss up to 10%.

I-18

3/7/2024

18

## Item 59 - Timber Superstructures

### Poor Condition

- Extensive Crack in timber beam
- 20% loss in cross section



**POOR.** Extensive decay, cracking, splitting or crushing of beams or stringers, or fire damage with main load carrying portions affected. Section loss up to 30%.

I-19

3/7/2024

19

## Item 59 - Timber Superstructures

### Serious Condition

- Sawn timber super and deck
- Fire damage
- Section loss at 35% in critical load carrying areas



**SERIOUS.** Severe decay, cracking, splitting or crushing of beams or stringers, or fire damage with major section loss up to 50% in critical load carrying portions of members. A further progression of problems noted for a condition rating of "4".

I-20

3/7/2024

20

## Item 59 - Timber Superstructures

### Critical Condition

- ❑ Sawn timber super and deck
- ❑ Decay & Partial Break of girder
- ❑ Section loss of 80% in critical load carrying area of single beam
- ❑ Multi girder cross section



**CRITICAL.** Beam ends may be crushed or split with settlement of deck. Any **further deterioration of problems noted for a condition rating of "3"**. Section loss over 50%, special feature inspection is required to allow bridge to remain open. The Bureau of Bridges and Structures shall be notified immediately.

I-21

3/7/2024

21

## Discussion

I-22

3/7/2024

22

# PPC DECK BEAMS

3/7/2024 IL NBI Refresher Course 2024

1

## Item 59 - PPC Deck Beams

### Precast Prestressed Concrete Deck Beams

- Characteristics of PPC Deck Beams
- Effect of overlays type on rating codes
- Sounding and scaling beams during inspection
- Key Indicators for PPC Deck Beams
- Determining Condition Ratings using Key Indicators


3/7/2024 KD-2

2

## Item 59 - PPC Deck Beams

### Precast Prestressed Concrete Deck Beams

- Introduced in the 1950's
- Advantages over non-prestressed concrete superstructures:
  - Eliminates need to form, pour and cure a deck
  - Shallow structural depth
  - Rapid construction



KD-3

3/7/2024

3

## Item 59 - PPC Deck Beams

### “Flexible Wearing Surface”

- Deck (Item 58) and Super (Item 59) are rated and coded the same
- Generally consist of bituminous or oil & chip overlays
- Longitudinal Cracks in the overlay usually indicate cracked shear keyways



KD-4

3/7/2024

4

## Item 59 - PPC Deck Beams

### “Rigid Wearing Surface”

- Thickness of Conc. overlay must be 4” or greater
- Concrete overlay must be reinforced
- Rate the overlay as the Deck (Item 58) and the beams as the Superstructure (Item 59)



KD-5

3/7/2024

5

## Item 59 - PPC Deck Beams

### Sounding

- Use hammer sounding to detect delaminated areas
- Delaminations have a distinctive “hollow or clacking” sound
- Sound concrete has a solid “pinging” sound
- Remove loose & delaminated concrete if practical to reduce the deterioration rate



KD-6

3/7/2024

6



## Item 59 - PPC Deck Beams

### General Notes:

Prestressing strands, reinforcement bars or wire mesh should be considered ineffective in areas where concrete is deteriorated or unsound (delaminated) to the level of the strands, bars or mesh

Post construction repair patches are considered delaminated and the PS strands beneath are considered ineffective



KD-7

3/7/2024

7

## Item 59 - PPC Deck Beams

### General Notes:

Shear keyway clamps are used at times to remediate differential beam movement

If the clamps are effectively causing the beams to work together and share LL, then they can be considered a good repair



KD-8

3/7/2024

8

## Item 59 - PPC Deck Beams

### General Notes:

#### PPC Deck Beams - 1 of 2

- Moderate/severe leaching cracks full width of beam
- Sounding indicated not delaminated yet but soft/dull
- Keyways deteriorated
- Not a salted route
- Super was rated a 5 during last inspection
- Beams failed at 2 bridge locations!
- This bridge received multiple loadings from single axle grain wagon prior to failure



KD-9

3/7/2024

9

## Item 59 - PPC Deck Beams

### General Notes:

#### PPC Deck Beams - 2 of 2

- Concrete crushed in top of beam, strands looked good
- Beam concrete cores showed strengths of 1.8, 2.8, 3.8 & 7.6ksi for 5.0ksi design strength
- Similar looking beam conditions have been found at other bridges
- Be sure to rate similar beams as if the cracked/leaching areas were delaminated!!



KD-10

3/7/2024

10

## Item 59 - PPC Deck Beams

### General Notes:

Prestressing strands adjacent to longitudinal cracks shall be considered as ineffective

The "end quarters of span" do not include the beam ends (last 3')



KD-11

3/7/2024

11

## Item 59 - PPC Deck Beams

### General Notes:

#### Another Example

Prestressing strands adjacent to longitudinal cracks shall be considered as ineffective

Note keyway leaking full length of beam

The dimensions stated on the following pages relate to the width of the cross section of a beam



KD-12

3/7/2024

12

### Item 59 - PPC Deck Beams

Key Indicators	Code	Description
	<ul style="list-style-type: none"> <li>▪ Cracks</li> <li>▪ Delams &amp; Spalls</li> <li>▪ Exposed Reinf &amp; Strands</li> <li>▪ Ineffective Keyways w/differential movement of beams</li> </ul>	8
7		GOOD. No beams with prestressing strands, stirrup reinforcement bars or wire mesh exposed. <b>Moderate cracking and leakage</b> may be present in keyways, but <b>no differential movement</b> occurring between deck beams.
6		<p>SATISFACTORY.</p> <p>Center half of span: No beams with prestressing strands, stirrup reinforcement or wire mesh bars exposed, no longitudinal cracking or spalling along the bottom of the beams.</p> <p>End quarters of span: No more than <b>2 strands or 3" of stirrup reinforcement bars or 3" of wire mesh exposed in the bottom of any beam.</b></p> <p>Larger widths of wire mesh may be exposed due to inadequate concrete cover occurring during manufacturing (up to 1/2" cover), <b>keyway cracking</b> may be evident <b>with wide spread leakage</b>, but <b>beams are still fully acting together.</b></p>

KD-13

3/7/2024

13

### Item 59 - PPC Deck Beams

Key Indicators	Code	Description
	<ul style="list-style-type: none"> <li>▪ Cracks</li> <li>▪ Delams &amp; Spalls</li> <li>▪ Exposed Reinf &amp; Strands</li> <li>▪ Ineffective Keyways w/differential movement of beams</li> </ul>	5

KD-14

3/7/2024

14

## Item 59 - PPC Deck Beams

Key Indicators		Code	Description
<ul style="list-style-type: none"> <li>Cracks</li> <li>Delams &amp; Spalls</li> <li>Exposed Reinf &amp; Strands</li> <li>Ineffective Keyways w/differential movement of beams</li> </ul>			<p>POOR.</p> <p>Center half of span: <b>Prestressed strands, stirrup reinforcement bars or wire mesh exposed</b> for no more than 1/2 the width of any beam bottom, spalling or delamination of the top of the beams down to the top reinforcement, one <b>longitudinal crack</b> in the bottom of any beam.</p> <p>End quarters of span: <b>Prestressed strands, stirrup reinforcement bars or wire mesh exposed</b> for no more than 1/2 the width of any beam bottom, two <b>longitudinal cracks</b> in the bottom of any beam.</p> <p>Beam ends (up to 3'): <b>Prestressed strands, stirrup reinforcement bars or wire mesh exposed</b> up to full width of adjacent beam bottom with no exposed strands in the second layer of strands and sound concrete above the bottom layer.</p> <p>Larger width of <b>wire mesh exposed</b> and actively corroding due to inadequate concrete cover occurring during manufacturing (up to 1/2" cover), <b>keyway has failed with groups of beams acting independently</b> of others.</p>
	4		

3/7/2024

KD-15

15

## Item 59 - PPC Deck Beams

Key Indicators		Code	Description
<ul style="list-style-type: none"> <li>Cracks</li> <li>Delams &amp; Spalls</li> <li>Exposed Reinf &amp; Strands</li> <li>Ineffective Keyways w/differential movement of beams</li> </ul>			<p>SERIOUS.</p> <p>Center half of span: <b>Prestressing strands, stirrup reinforcement bars or wire mesh exposed</b> for no more than 1/2 the width of any beam bottom, two <b>longitudinal cracks</b> in the bottom of any beam, combinations of deterioration in condition rating "4".</p> <p>End quarters of span: <b>Prestressing strands, stirrup reinforcement bars or wire mesh exposed</b> for no more than 2/3 the width of any beam bottom, combination of deterioration in condition rating "4".</p> <p>Beam ends (up to 3'): <b>Prestressed strands, stirrup reinforcement bars or wire mesh exposed</b> full width of adjacent beam bottom with <b>exposed strands</b> in the second layer of strands or unsound concrete above the bottom layer.</p> <p><b>Keyways have failed causing 3 or 4 beams to act independently</b> from others.</p>
	3		

3/7/2024

KD-16

16

## Item 59 - PPC Deck Beams

### Key Indicators

- Cracks
- Delams & Spalls
- Exposed Reinf & Strands
- Ineffective Keyways w/differential movement of beams

Code	Description
2	CRITICAL. Similar to but <b>more serious and extensive</b> than what is described for a condition rating of "3", <b>transverse cracks</b> full width in the bottom of the beams, <b>keyways have failed</b> causing 1 or 2 beams to act independently from others. Structural elements that are judged to be in critical condition must receive special inspections in order for the structure to remain open to traffic. The Bureau of Bridges and Structures shall be notified immediately.
1	"IMMINENT" FAILURE. Superstructure in "imminent failure" condition requiring bridge closure or temporary measures to allow structure to remain open.
0	FAILED. Superstructure that has failed and is beyond repair, requiring bridge closure.

KD-17

3/7/2024

17

## Item 59 - PPC Deck Beams

**When does the condition rating of an individual deck beam effect that of the whole superstructure if the other beams are in better condition?**

- *If one or more beams meets the condition rating requirements of a "4" or lower rating, this condition rating should be applied to the superstructure as a whole*
- *The condition rating of "4" POOR CONDITION was selected as this is the level where loss of Structural Load Capacity generally begins to occur*
- *An initial rating of "4" or below will trigger a Load Rating Inspection by IDOT*

KD-18

3/7/2024


18



## Item 59 - PPC Deck Beams

**New Construction**

**No deficiencies**



**New Deck Beam – Allowed first inspection only**

KD-19


3/7/2024

19

## Item 59 - PPC Deck Beams

**Very Good Condition**

- No Deficiencies
- Not 1<sup>st</sup> inspection



**VERY GOOD. No notable problems.**

KD-20

3/7/2024

20

## Item 59 - PPC Deck Beams

### Good Condition

- Cracks in the RC overlay (0.02")
- No noticeable keyway leakage
- Rigid wearing surface would be rated as the Deck (Item 58)
- Deck would be rated "4" due to widespread map cracking.
- Item 59 is a "7"



GOOD. No beams with prestressing strands, stirrup reinforcement bars or wire mesh exposed. **Moderate cracking** and leakage **may be present in keyways**, but no differential movement occurring between deck beams.

KD-21

3/7/2024

21

## Item 59 - PPC Deck Beams

### Good Condition

- Underside of the Superstructure in the previous slide
- Reflective cracking in the rigid WS may indicate cracked or failed keyways



GOOD. No beams with prestressing strands, stirrup reinforcement bars or wire mesh exposed. **Moderate cracking** and leakage **may be present in keyways**, but no differential movement occurring between deck beams.


KD-22

22

## Item 59 - PPC Deck Beams

**Good Condition**

- Moderate keyway leakage with efflorescence
- Beams are still acting together



**GOOD.** No beams with prestressing strands, stirrup reinforcement bars or wire mesh exposed. **Moderate cracking and leakage may be present in keyways, but no differential movement occurring between deck beams.**

KD-23


3/7/2024

23

## Item 59 - PPC Deck Beams

**Satisfactory Condition**

- Keyway leakage
- Beams still acting together
- Inadequate concrete cover has exposed mesh on one beam
- Verify exposed wire is not a prestress strand



**SATISFACTORY.** Center half of span: No beams with prestressing strands, stirrup reinforcement or wire mesh bars exposed, no longitudinal cracking reinforcement or wire mesh bars exposed, no longitudinal cracking or spalling along the bottom of the beams. End quarters of span: No more than **2 strands or 3" of stirrup reinforcement bars or 3" of wire mesh exposed in the bottom of any beam.** Larger widths of **wire mesh may be exposed** due to inadequate concrete cover occurring during manufacturing (up to 1/2" cover), **keyway cracking** may be evident with **wide spread leakage**, but beams are still fully acting together.

KD-24

3/7/2024

24

## Item 59 - PPC Deck Beams

### Fair Condition

- Spall up to 6" wide in the end quarter of the span with reinforcement exposed
- Spall with reinforcement exposed near the beam end



FAIR. Center half of span: No more than 2 strands or 3" of stirrup reinforcement bars or 3" of wire mesh exposed in any beam, longitudinal cracking or spalling limited to one edge with no other defects exposing reinforcement, wire mesh or strands. End quarters of span: No more than 4 strands or 6" of stirrup reinforcement bars or 6" of wire mesh exposed in the bottom of any beam, no more than one longitudinal crack in any beam without any other defect. Beam ends (up to 3'): Prestressed strands, stirrup reinforcement bars or wire mesh exposed up to full width of any beam bottom. Larger widths of wire mesh may be exposed due to inadequate concrete cover occurring during manufacturing (up to 1/2" cover), keyway cracking with extensive leakage and evidence that beams are beginning to act independently of each other.

KD-25

3/7/2024

25

## Item 59 - PPC Deck Beams

### Fair Condition

- Spall full width on the beam end with reinforcement exposed
- No other defects



FAIR. Center half of span: No more than 2 strands or 3" of stirrup reinforcement bars or 3" of wire mesh exposed in any beam, longitudinal cracking or spalling limited to one edge with no other defects exposing reinforcement, wire mesh or strands. End quarters of span: No more than 4 strands or 6" of stirrup reinforcement bars or 6" of wire mesh exposed in the bottom of any beam, no more than one longitudinal crack in any beam without any other defect. Beam ends (up to 3'): Prestressed strands, stirrup reinforcement bars or wire mesh exposed up to full width of any beam bottom. Larger widths of wire mesh may be exposed due to inadequate concrete cover occurring during manufacturing (up to 1/2" cover), keyway cracking with extensive leakage and evidence that beams are beginning to act independently of each other.

KD-26

3/7/2024

26

## Item 59 - PPC Deck Beams

### Poor Condition

- Spalls with reinforcement exposed
- Width is 8" of the 36" beam width (less than 1/3 of the beam width)
- Location of defect is near center half of span



POOR. Center half of span: Prestressed strands, stirrup reinforcement bars or wire mesh exposed for no more than 1/2 the width of any beam bottom, spalling or delamination of the top of the beams down to the top reinforcement, one longitudinal crack in the bottom of any beam. End quarters of span: Prestressed strands, stirrup reinforcement bars or wire mesh exposed for no more than 1/2 the width of any beam bottom, two longitudinal cracks in the bottom of any beam. Beam ends (up to 3'): Prestressed strands, stirrup reinforcement bars or wire mesh exposed up to full width of adjacent beam bottom with no exposed strands in the second layer of strands and sound concrete above the bottom layer. Larger width of wire mesh exposed and actively corroding due to inadequate concrete cover occurring during manufacturing (up to 1/2" cover), keyway has failed with groups of beams acting independently of others.

KD-27

3/7/2024

27

## Item 59 - PPC Deck Beams

### Poor Condition

- Spalls with reinforcement exposed
- Full width of adjacent beam ends



POOR. Center half of span: Prestressed strands, stirrup reinforcement bars or wire mesh exposed for no more than 1/2 the width of any beam bottom, spalling or delamination of the top of the beams down to the top reinforcement, one longitudinal crack in the bottom of any beam. End quarters of span: Prestressed strands, stirrup reinforcement bars or wire mesh exposed for no more than 1/2 the width of any beam bottom, two longitudinal cracks in the bottom of any beam. Beam ends (up to 3'): Prestressed strands, stirrup reinforcement bars or wire mesh exposed up to full width of adjacent beam bottom with no exposed strands in the second layer of strands and sound concrete above the bottom layer. Larger width of wire mesh exposed and actively corroding due to inadequate concrete cover occurring during manufacturing (up to 1/2" cover), keyway has failed with groups of beams acting independently of others.

KD-28

3/7/2024

28



## Item 59 - PPC Deck Beams

### Serious Condition

- Spalls or delaminations
- Width is 15" of 36" beam width ( $> 1/3 < 1/2$  of width)
- Location of defect is in center half span



SERIOUS. Center half of span: **Prestressing strands, stirrup reinforcement bars or wire mesh exposed** for no more than  $1/2$  the width of any beam bottom, two longitudinal cracks in the bottom of any beam, combinations of deterioration in condition rating "4". End quarters of span: Prestressing strands, stirrup reinforcement bars or wire mesh exposed for no more than  $1/2$  the width of any beam bottom, combination of deterioration in condition rating "4". Beam ends (up to 3'): Prestressed strands, stirrup reinforcement bars or wire mesh exposed full width of adjacent beam bottom with exposed strands in the second layer of strands or unsound concrete above the bottom layer. Keyways have failed causing 3 or 4 beams to act independently from others.

KD-29

3/7/2024

29

## Item 59 - PPC Deck Beams

### Serious Condition

- Spalls or delaminations
- Width is 14" (8" + 6") of the 36" beam width ( $> 1/3 < 1/2$  of width)
- Located in center half of span
- Keyway failure indicated by observed differential movement



SERIOUS. Center half of span: **Prestressing strands, stirrup reinforcement bars or wire mesh exposed** for no more than  $1/2$  the width of any beam bottom, two longitudinal cracks in the bottom of any beam, combinations of deterioration in condition rating "4". End quarters of span: Prestressing strands, stirrup reinforcement bars or wire mesh exposed for no more than  $1/2$  the width of any beam bottom, combination of deterioration in condition rating "4". Beam ends (up to 3'): Prestressed strands, stirrup reinforcement bars or wire mesh exposed full width of adjacent beam bottom with exposed strands in the second layer of strands or unsound concrete above the bottom layer. **Keyways have failed** causing 3 or 4 beams to act independently from others.

KD-30

3/7/2024

30



## Item 59 - PPC Deck Beams

### Critical Condition

- Spalls or delaminations
- Combined width is 26" of the 36" beam width (> 1/2 of width)
- Several keyways have failed with observed differential movement



**CRITICAL.** Similar to but more serious and extensive than what is described for a condition rating of "3", transverse cracks full width in the bottom of the beams, **keyways have failed causing 1 or 2 beams to act independently** from others. Structural elements that are judged to be in critical condition must receive special inspections in order for the structure to remain open to traffic. **The Bureau of Bridges and Structures shall be notified immediately.**

KD-31

3/7/2024

31

## Item 59 - PPC Deck Beams

- Example of beams acting independently due to keyway failure
- Bituminous overlay becomes dislodged by differential movement of beams



KD-32

32

## Item 59 - PPC Deck Beams

### Critical Condition

- Spalls or delaminations
- Width extends 34" across the 36" beam width ( $> \frac{1}{2}$  width)
- Exposed prestressed strands
- Keyway failure
- Notify BBS immediately



**CRITICAL.** Similar to but more serious and extensive than what is described for a condition rating of "3", transverse cracks full width in the bottom of the beams, **keyways have failed** causing 1 or 2 beams to act independently from others. Structural elements that are judged to be in critical condition must receive special inspections in order for the structure to remain open to traffic. **The Bureau of Bridges and Structures shall be notified immediately.**

KD-33

3/7/2024

# PPC I-BEAMS

3/7/2024


IL NBI Refresher Course 2024

1

## Item 59 – PPC I-Beams

### Prestressed Concrete I-Beams

- Used since the 1950's
- "I" or "Bulb T" shape
- High Strength Concrete (5-10 ksi typically)
- Newer hybrid sections introduced by IDOT in 2015 with larger sections added in 2021
- Depth ranges from 35"- 90"



KL-2

3/7/2024


2

## Item 59 – PPC I-Beams

### Prestressed Concrete I-Beam

- The condition of the beam “PERIMETER” is used to help determine the condition rating
- It is the bottom flange length enclosing the prestressing strands

Perimeter



3/7/2024

KI-3

3

## Item 59 – PPC I-Beams

### Sounding

- Use hammer sounding to detect delaminated areas
- Delaminations have a distinctive “hollow or clacking” sound
- Sound concrete has a solid “pinging” sound



3/7/2024

KI-4

4

## Item 59 – PPC I-Beams

### Delams, Spalls & Strikes

#### Look Around:

- Current & old deck drain locations
- Beneath transverse deck joints
- Adjacent to current or old longitudinal deck joints
- Above traffic lanes



KI-5

3/7/2024

5

## Item 59 – PPC I-Beams

### Shrinkage Cracks

### or Shear Cracks

### For Shrinkage Cracks

#### Look Around:

- Beam ends
- Look for tight cracks starting from the beam ends
- Moderate amounts = 7 rating



KI-6

3/7/2024

6

## Item 59 – PPC I-Beams

**Shrinkage Cracks  
or Shear Cracks**

**For Shear Cracks**

**Look Around:**

- Beam end quarter or beam ends
- Look for tight cracks extending up at an angle in the beam
- Shear cracks = **3** rating

KI-7

3/7/2024

7

## Item 59 – PPC I-Beams

**Key Indicators**

- Cracks
- Delams & Spalls
- Exposed Reinf & Strands
- Tight Shear Cracks in End Quarters

Code	Description
8	VERY GOOD. No notable problems.
7	GOOD. No beams with prestressing strands, stirrup reinforcement bars or wire mesh exposed. <b>Minor shrinkage or release cracks</b> may be present. <b>Minor map cracking</b> at drains with sound concrete.
6	SATISFACTORY. Center half of span: No beams with prestressing strands, stirrup reinforcement exposed.  End quarters of span: No more than <b>2 strands or 3" of stirrup reinforcement bars exposed</b> in the bottom of any beam.  Beam ends (up to 3'): <b>Prestressed strands or stirrup reinforcement bars exposed</b> up to 1/2 the perimeter of the bottom flange of any beam.  Larger width of stirrups may be exposed due to inadequate concrete cover occurring during manufacturing (up to 1/2 cover). Webs may be spalled with exposed stirrups and only surface rust.

KI-8

3/7/2024

8



## Item 59 – PPC I-Beams

### Key Indicators

- Cracks
- Delams & Spalls
- Exposed Reinf & Strands
- Tight Shear Cracks in End Quarters

Code	Description
5	FAIR. Center half of span: <b>Prestressed strands or stirrup reinforcement bars exposed</b> for no more than 1/4 the perimeter of the bottom flange of any beam.
	End quarters of span: <b>Prestressed strands or stirrup reinforcement bars exposed</b> for no more than 1/3 the perimeter of the bottom flange of any beam.
	Beam ends (up to 3'): <b>Prestressed strands or stirrup reinforcement bars exposed</b> from 1/2 to full perimeter of the bottom flange of any beam.
	Larger areas of stirrup may be exposed due to inadequate concrete cover that occurs during manufacturing (up to 1/2 cover). Webs may be spalled with exposed stirrups minor section loss.

KI-9

3/7/2024

9

## Item 59 – PPC I-Beams

### Key Indicators

- Cracks
- Delams & Spalls
- Exposed Reinf & Strands
- Tight Shear Cracks in End Quarters

Code	Description
4	POOR. Center half of span: <b>Prestressed strands or stirrup reinforcement bars exposed</b> for no more than 2/3 the perimeter of the bottom flange of any beam.
	End quarters of span: <b>Prestressed strands or stirrup reinforcement bars exposed</b> up to full perimeter of the bottom flange of any beam. No strands are exposed inside the exterior perimeter of strands.
	Beam ends (up to 3'): <b>Prestressed strands or stirrup reinforcement bars exposed</b> full perimeter of the bottom flange of any beam with some <b>strands exposed</b> inside the exterior perimeter of strands.
	Webs are spalled with exposed stirrups with up to 30% section loss at ends of beams.

KI-10

3/7/2024

10

## Item 59 – PPC I-Beams

### Key Indicators

- Cracks
- Delams & Spalls
- Exposed Reinf & Strands
- Tight Shear Cracks in End Quarters

Code	Description
3	<p>SERIOUS. Center half of span: <b>Prestressed strands or stirrup reinforcement bars</b> exposed up to full perimeter of the bottom flange of any beam. No strands are exposed inside the exterior perimeter of strands.</p> <p>End quarters of span: <b>Prestressing strands, stirrup reinforcement bars exposed</b> for the full perimeter of the bottom flange of any beam with some <b>strands exposed</b> inside the exterior perimeter of strands.</p> <p>Hairline transverse <b>cracks</b> in bottom of beams or <b>hairline vertical/diagonal shear cracks in beam webs</b> may be developing.</p>

KI-11

3/7/2024

11

## Item 59 – PPC I-Beams

### Key Indicators

- Cracks
- Delams & Spalls
- Exposed Reinf & Strands
- Tight Shear Cracks in End Quarters

Code	Description
2	<p>CRITICAL. <b>Similar to but more serious and extensive</b> than what is described for a condition rating of “3”. Structural elements that are judged to be in critical condition must receive special inspections in order for the structure to remain open to traffic. <b>Measurable shear or transverse cracks</b>. The Bureau of Bridges and Structures shall be notified immediately.</p>

KI-12

3/7/2024

12

## Item 59 – PPC I-Beams

### New Construction

- No defects
- First inspection



New PPC I-Beam – Allowed first inspection only

KI-13

3/7/2024

13

## Item 59 – PPC I-Beams

### Very Good

- No deficiencies
- Second inspection



VERY GOOD. No notable problems.

KI-14

3/7/2024

14

## Item 59 – PPC I-Beams

**Good**

Minor shrinkage cracks present in beams



**GOOD.** No beams with prestressing strands, stirrup reinforcement bars or wire mesh exposed. **Minor shrinkage** or release **cracks** may be present. Minor map cracking at drains with sound concrete.

KI-15

3/7/2024

15

## Item 59 – PPC I-Beams

**Satisfactory**

Three strands exposed at the end of the beam



**SATISFACTORY.** Center half of span: No beams with prestressing strands, stirrup reinforcement exposed. End quarters of span: No more than 2 strands or 3" of stirrup reinforcement bars exposed in the bottom of any beam. Beam ends (up to 3'): **Prestressed strands or stirrup reinforcement bars exposed** up to 1/2 the perimeter of the bottom flange of any beam. Larger width of stirrups may be exposed due to inadequate concrete cover occurring during manufacturing (up to 1/2 cover). Webs may be spalled with exposed stirrups and only surface rust.

KI-16

3/7/2024

16

### Item 59 – PPC I-Beams



Two strands of reinforcement bars exposed in the bottom of beam



No beams with reinforcement exposed at center span

3/7/2024

KI-17

17

### Item 59 – PPC I-Beams

#### Fair

Reinforcement bars exposed for 30% of perimeter of bottom flange in end quarter of span



FAIR. Center half of span: Prestressed strands or stirrup reinforcement bars exposed for no more than 1/4 the perimeter of the bottom flange of any beam. End quarters of span: Prestressed strands or stirrup reinforcement bars exposed for no more than 1/3 the perimeter of the bottom flange of any beam. Beam ends (up to 3'): Prestressed strands or stirrup reinforcement bars exposed from 1/2 to full perimeter of the bottom flange of any beam. Larger areas of stirrup may be exposed due to inadequate concrete cover that occurs during manufacturing (up to 1/2 cover). Webs may be spalled with exposed stirrups minor section loss.

3/7/2024

KI-18

18

### Item 59 – PPC I-Beams



6

No beams with reinforcement exposed at center span



5

Spall with 4 exposed strands in the end quarter

KI-19

3/7/2024

19

### Item 59 – PPC I-Beams

#### Poor

Reinforcement bars exposed for more than 55% of perimeter of bottom flange in end quarter



4

12/04/20

POOR. Center half of span: Prestressed strands or stirrup reinforcement bars exposed for no more than 2/3 the perimeter of the bottom flange of any beam. End quarters of span: **Prestressed strands or stirrup reinforcement bars exposed** up to full perimeter of the bottom flange of any beam. No strands are exposed inside the exterior perimeter of strands. Beam ends (up to 3'): Prestressed strands or stirrup reinforcement bars exposed full perimeter of the bottom flange of any beam with some strands exposed inside the exterior perimeter of strands. Webs are spalled with exposed stirrups with up to 30% section loss at ends of beams.

KI-20

3/7/2024

20



## Item 59 – PPC I-Beams

### Serious

Strands exposed for full perimeter of bottom flange in center half of span



**SERIOUS.** Center half of span: Prestressed strands or stirrup reinforcement bars exposed up to full perimeter of the bottom flange of any beam. No strands are exposed inside the exterior perimeter of strands. End quarters of span: Prestressing strands, stirrup reinforcement bars exposed for the full perimeter of the bottom flange of any beam with some strands exposed inside the exterior perimeter of strands. Hairline transverse cracks in bottom of beams or hairline vertical/diagonal shear cracks in beam webs may be developing

KI-21

3/7/2024

21

## Item 59 – PPC I-Beams

### Serious

Tight diagonal shear cracks in beam web at the beam end quarter & beam end.



**SERIOUS.** Center half of span: Prestressed strands or stirrup reinforcement bars exposed up to full perimeter of the bottom flange of any beam. No strands are exposed inside the exterior perimeter of strands. End quarters of span: Prestressing strands, stirrup reinforcement bars exposed for the full perimeter of the bottom flange of any beam with some strands exposed inside the exterior perimeter of strands. Hairline transverse cracks in bottom of beams or hairline vertical/diagonal shear cracks in beam webs may be developing

KI-22

3/7/2024

22

## Item 59 – PPC I-Beams

### Critical

- Prestressing strands exposed over full perimeter
- Open shear cracks
- Damage in middle half of beam



**CRITICAL.** Similar to but **more serious and extensive** than what is described for a condition rating of "3". Structural elements that are judged to be in critical condition must receive special inspections in order for the structure to remain open to traffic. **Measurable shear or transverse cracks.** The Bureau of Bridges and Structures shall be notified immediately.

KI-23

3/7/2024

23

## Item 59 – PPC I-Beams

### Imminent Failure

- Exterior beam has failed
- Strands exposed for full perimeter of bottom flange at center span



**IMMINENT FAILURE.** **Condition requiring bridge closure or temporary measures** to allow structure to remain open

KI-24

3/7/2024

24

# REVIEW


KI-25

25

## Item 59 – PPC I-Beams

**KI-1: How would you rate this Superstructure?**  
Minor shrinkage cracks present

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
10. N



3/7/2024

KI-26

26

## Item 59 – PPC I-Beams

**Good**

**Minor shrinkage cracks present**



**GOOD.** No beams with prestressing strands, stirrup reinforcement bars or wire mesh exposed. **Minor shrinkage or release cracks may be present.** Minor map cracking at drains with sound concrete.

KI-27

3/7/2024

27

## Item 59 – PPC I-Beams

**KI-2: How would you rate this Superstructure?**

- 1. **1**
- 2. **2**
- 3. **3**
- 4. **4**
- 5. **5**
- 6. **6**
- 7. **7**
- 8. **8**
- 9. **9**
- 10. **N**

Reinforcement bars exposed for 22% of the perimeter of the bottom flange in the center half. The web is spalled with minor section loss to the stirrups.



KI-28

3/7/2024

28

## Item 59 – PPC I-Beams

### Fair

Reinforcement bars exposed for 22% of perimeter of bottom flange in center half.

The web is spalled with minor section loss to stirrups.



**FAIR.** Center half of span: Prestressed strands or stirrup reinforcement bars exposed for no more than ¼ of the perimeter of the bottom flange of any beam. End quarters of span: Prestressed strands or stirrup reinforcement bars exposed for no more than 1/3 the perimeter of the bottom flange of any beam. Beam ends (up to 3'): Prestressed strands or stirrup reinforcement bars exposed from ¼ to full perimeter of the bottom flange of any beam. Larger areas of stirrup may be exposed due to inadequate concrete cover that occurs during manufacturing (up to ½ cover). Webs may be spalled with exposed stirrups minor section loss.

KI-29

3/7/2024

29

## Item 59 – PPC I-Beams

### KI-3: How would you rate this Superstructure?

1. 1
2. 2
3. 3
4. 4
5. 5
6. 6
7. 7
8. 8
9. 9
10. N

Tight diagonal cracks are found in the beam webs near the beam ends.



KI-30


3/7/2024

30

## Item 59 – PPC I-Beams

### Serious

Tight diagonal cracks are found in the beam webs near the beam ends and exiting in the end of the beam.



**SERIOUS.** Center half of span: Prestressed strands or stirrup reinforcement bars exposed up to full perimeter of the bottom flange of any beam. No strands are exposed inside the exterior perimeter of strands. End quarters of span: Prestressing strands, stirrup reinforcement bars exposed for the full perimeter of the bottom flange of any beam with some strands exposed inside the exterior perimeter of strands. Hairline transverse cracks in bottom of beams or hairline vertical/diagonal shear cracks in beam webs may be developing

KI-31

3/7/2024

31

## Item 59 – PPC I-Beams

### KI-4: How would you rate this Superstructure?

- 1. 1
- 2. 2
- 3. 3
- 4. 4
- 5. 5
- 6. 6
- 7. 7
- 8. 8
- 9. 9
- 10. N

Reinforcement bars exposed for 58% of the perimeter of the bottom flange at center half of span



KI-32

3/7/2024

32



## Item 59 – PPC I-Beams

### Poor

Reinforcement bars exposed for 58% of perimeter of bottom flange at center span



POOR. Center half of span: Prestressed strands or stirrup reinforcement bars exposed for no more than 2/3 the perimeter of the bottom flange of any beam. End quarters of span: Prestressed strands or stirrup reinforcement bars exposed up to full perimeter of the bottom flange of any beam. No strands are exposed inside the exterior perimeter of strands. Beam ends (up to 3'): Prestressed strands or stirrup reinforcement bars exposed full perimeter of the bottom flange of any beam with some strands exposed inside the exterior perimeter of strands. Webs are spalled with exposed stirrups with up to 30% section loss at ends of beams.

KI-33

3/7/2024

33

## Item 59 – PPC I-Beams

### KI-5: How would you rate this Superstructure?

- 1. 1
- 2. 2
- 3. 3
- 4. 4
- 5. 5
- 6. 6
- 7. 7
- 8. 8
- 9. 9
- 10. N

Shrinkage Cracks with no reinforcement exposed



KI-34

3/7/2024

34

## Item 59 – PPC I-Beams

**Good**

Shrinkage cracks with no reinforcement exposed



**GOOD.** No beams with prestressing strands, stirrup reinforcement bars or wire mesh exposed. **Minor shrinkage** or release **cracks** may be present. Minor map cracking at drains with sound concrete.

KI-35

3/7/2024

35

## Discussion

KI-36

3/7/2024

36

# STEEL SUPERSTRUCTURES

3/7/2024 IL NBI Refresher Course 2024

1

## Item 59 - Steel Superstructures

- **Types of Steel Structures and Unique Details**
- **Common Missed Deficiencies**
- **Section Remaining vs. Section Loss**
- **Condition Ratings**

3/7/2024 I-2

2

## Item 59 - Steel Superstructures

### Types of Steel Superstructures

#### Rolled I-Beams

- Various standard sizes:
  - 18" – 36" depths common in bridges (3" increments)
  - 40" & 44" also available
- May have bearing stiffeners
- Common in short to mid span steel bridges



I-3

3/7/2024

3

## Item 59 - Steel Superstructures

### Types of Steel Superstructures

#### Welded Girders (I-shape)

- Made of plates welded together
- Width and thickness of flanges and webs can be varied
- Usually have bearing stiffeners
- Depth of web typically greater than 36"



I-4

3/7/2024

4

## Item 59 - Steel Superstructures

### Types of Steel Superstructures

#### Riveted Girder (I-shape)

- ▣ Made up of plates and angles riveted together
- ▣ Width and thickness of flanges and webs can be varied
- ▣ Usually have bearing stiffeners
- ▣ Often have intermediate stiffeners



I-5

3/7/2024


5

## Item 59 - Steel Superstructures

### Types of Steel Superstructures

#### Steel Box Girders

- ▣ Rectangular or trapezoidal cross section
- ▣ Commonly used for curved bridges
- ▣ Fracture Critical Inspection should include both inside and outside of box
- ▣ Confined Space Procedures?



I-6

3/7/2024

6

## Item 59 - Steel Superstructures

### Types of Steel Superstructures

#### Steel Two-Girder System

- ▣ May be riveted or welded
- ▣ Floor system may consist of floorbeams and stringers
- ▣ Through Girders fall in this category
- ▣ They are Fracture Critical (FC) Members or Nonredundant Steel Tension Members (NSTM)



3/7/2024


I-7

7

## Item 59 - Steel Superstructures

### Types of Steel Superstructures

- ▣ **Steel Trusses**
  - Used since the early 1800's
  - Structure made of triangles
  - Two parallel trusses
  - Trusses are the main load-carrying members
- ▣ **Three Main Types**
  - Through
  - Pony
  - Deck



3/7/2024

I-8

8



## Item 59 - Steel Superstructures

### Types of Steel Superstructures

#### Steel Arches

- ▣ Constructed since the late 1800's
- ▣ 3 Types
  - Deck
  - Through
  - Tied
- ▣ Tension chord, hangers & floor beams – typ. FC/NSTM



I-9

3/7/2024


9

## Item 59 - Steel Superstructures

### Unusual Details

#### Pin and Hanger

- ▣ Used on Multi-span bridges prior to 1970
- ▣ Moves expansion joints away from abutments and piers
- ▣ Simplified analysis
- ▣ No longer used in design



I-10

3/7/2024

10

## Item 59 - Steel Superstructures

### Unusual Details

#### Pin Connection

Single pin used without hanger bars to allow rotation only



I-11

3/7/2024


11

## Item 59 - Steel Superstructures

### Unusual Details

#### Steel Eyebars

- ▣ Eyebars are tension only members that require pins for end connections.
- ▣ Found on older truss bridges or suspension chain bridges



I-12

3/7/2024

12

## Item 59 - Steel Superstructures

### Common Missed Deficiencies

- Section loss at beam ends below transverse deck joints
- Look for heavy section loss in webs and in the bearing area
- For **ratings  $\leq 3$**  due to web section loss at the bearing area PM's are responsible for **installing/recommending wood blocking** between flanges to resist web crushing (July 2017)



I-13

3/7/2024

13

## Item 59 - Steel Superstructures

### Common Missed Deficiencies

- Section loss along the bottom of the web and
- Section loss along the top of the bottom flange
- Section loss around diaphragm connections



I-14

3/7/2024

14

## Item 59 - Steel Superstructures

### Common Missed Deficiencies

#### Defects Hidden by Pack Rust

- ❑ Superstructure rating had just been lowered from a 5 to a 4
- ❑ The condition of the floor stringers was not considered in the rating
- ❑ Actual super rating was a 1 !!



3/7/2024


15

## Item 59 - Steel Superstructures

### Common Missed Deficiencies

#### Cracks at Coped or Dapped Ends

- ❑ Connection may have been designed as a pinned
- ❑ The web may be carrying moment due to stiffness resulting from the depth of the connection
- ❑ Section loss can increase potential for cracks



3/7/2024


16

## Item 59 - Steel Superstructures

### Common Missed Deficiencies

### Cracks at Connections

Cracks can occur at rigid connections of transverse members to thin webs due to out-of-plane bending



I-17



3/7/2024

17

## Item 59 - Steel Superstructures

### Common Missed Deficiencies

Section loss in truss members and gusset plates at connections



I-18

3/7/2024

18

## Item 59 - Steel Superstructures

### Section Loss Measurements

- Steel Section Loss is measured as a % loss in the area of the original undamaged cross section of the **critical portion of a member**
- IDOT looks at Section Loss in **3 separate zones** for a typical flexural steel member:
  - Flexure zone
  - Shear zone
  - Bearing zone
- Pure Tension or Compression members are typically evaluated over the full section area
- See the IDOT BB&S Website for a webinar on Calculating Steel SL

I-19

3/7/2024


19

## Item 59 - Steel Superstructures

### Section Loss Measurements

#### FLEXURE ZONE:

- Section Loss is typically measured as the % loss in the area of **either one** of the flange cross sections
- A hole in a member is not necessarily 100% section loss
- Any web SL is not included in the % calculation for comparison to the SIP criteria



I-20

3/7/2024

20




## Item 59 - Steel Superstructures

### Section Loss Measurements

#### SHEAR ZONE:

- Section Loss is typically measured as the % loss in the area of the **total web cross section**
- A hole in a member is not necessarily 100% section loss
- Any flange SL is not included in the % calculation for comparison to the SIP criteria



I-21

3/7/2024


21

## Item 59 - Steel Superstructures

### Section Loss Measurements

#### BEARING ZONE:

- Section Loss is typically measured as the % loss in the **area of the web cross section located directly above the bearing**
- A hole in a member is not necessarily 100% section loss



I-22

3/7/2024


22

## Item 59 - Steel Superstructures

### Section Loss Measurements

#### TENSION & COMPRESSION MEMBERS:

- Section Loss is typically measured as the % loss in the total area of the member cross section
- A hole in a member is not necessarily 100% section loss



I-23

3/7/2024

23

## Item 59 - Steel Superstructures

### Key Indicators

#### □ Section Loss

#### □ Cracks

Code	Description
N	Culvert.
9	New superstructure.
8	VERY GOOD. No visible rust.
7	GOOD. Some rust may be present but without any section loss.
6	SATISFACTORY. Initial <b>section loss</b> (minor pitting, scaling, or flaking) up to 2% section loss.
5	FAIR. Initial <b>section loss</b> up to 10% in critical areas, fatigue or <b>out-of-plane bending cracks</b> may be present in secondary members, arrested fatigue <b>cracks</b> may be present in primary members, hinges may be showing minor corrosion problems, anchor bolt(s) may be missing.

I-24

3/7/2024

24

## Item 59 - Steel Superstructures

### Key Indicators

- ▣ Section Loss
- ▣ Cracks

Code	Description
4	POOR. <b>Section loss</b> up to 30% in critical area, <b>fatigue or out-of-plane bending cracks</b> may be present in primary members, previously <b>arrested fatigue cracks</b> propagating beyond arresting holes in primary members, <b>fatigue cracks</b> in secondary members throughout the bridge, <b>anchor bolts or pintles broken</b> on rocker bearings <u>with an offset of 1/2" or more between the rocker and the bearing or sole plates.</u>
3	SERIOUS. Advanced <b>section loss</b> up to 50%, extensive perpendicular to stress fatigue or out of plane bending <b>cracks</b> in primary members.
2	CRITICAL. Severe <b>section loss</b> over 50% requires special inspections, temporary supports or repairs may be required to remain open to traffic. The Bureau of Bridges and Structures shall be notified immediately.
1	Superstructure in "imminent failure" condition requiring bridge closure or temporary measures to allow structure to remain open.
0	Superstructure that has failed and is beyond repair, requiring bridge closure.


3/7/2024
I-25

25

## Item 59 - Steel Superstructures

### New Construction

No deficiencies



New superstructure – Allowed first inspection only

3/7/2024
I-26

26

## Item 59 - Steel Superstructures

### Very Good Condition

- No deficiencies
- Not new construction
- Note: Weathering Steel**



VERY GOOD. No "excessive" rust.

I-27

3/7/2024

27

## Item 59 - Steel Superstructures

### Good Condition

- Minor rust on the bottom flanges
- No section loss



GOOD. **Some rust** may be present but **without any section loss**.

I-28

3/7/2024

28

## Item 59 - Steel Superstructures

### Good Condition

- Minor rust on bottom flange
- No section loss



**GOOD.** Some rust may be present but **without any section loss.**

3/7/2024

I-29

29

## Item 59 - Steel Superstructures

### Satisfactory Condition

- Initial section loss in non-critical area of bottom flange
- Rust stains on web resulting from rust on secondary member



**SATISFACTORY.** Initial section loss (minor pitting, scaling, or flaking) up to 2% section loss.

3/7/2024

I-30

30

## Item 59 - Steel Superstructures

### Satisfactory Condition

- Section loss on flanges of diaphragm (secondary member)
- No section loss on girder web



**SATISFACTORY.** Initial **section loss** (minor pitting, scaling, or flaking) up to 2% section loss.

I-31

3/7/2024

31

## Item 59 - Steel Superstructures

### Fair Condition

- Minor cracks
- Arrester holes have been drilled in web to prevent further progression of cracks



**FAIR.** Initial **section loss** up to 10% in critical areas, fatigue or **out-of-plane bending cracks** may be present in secondary members, arrested fatigue **cracks** may be present in primary members, hinges may be showing minor corrosion problems, anchor bolt(s) may be missing.

I-32

3/7/2024

32



## Item 59 - Steel Superstructures

### Fair Condition

8% section loss at bottom flange and on web of girder



FAIR. Initial **section loss** up to 10% in critical areas, fatigue or out-of-plane bending cracks may be present in secondary members, arrested fatigue cracks may be present in primary members, hinges may be showing minor corrosion problems, anchor bolt(s) may be missing.

I-33

3/7/2024

33

## Item 59 - Steel Superstructures

### Fair Condition

7% Section loss along the lateral edge bracing



FAIR. Initial **section loss** up to 10% in critical areas, fatigue or out-of-plane bending cracks may be present in secondary members, arrested fatigue cracks may be present in primary members, hinges may be showing minor corrosion problems, anchor bolt(s) may be missing.

I-34

3/7/2024

34

## Item 59 - Steel Superstructures

### Poor Condition

25% section loss  
in the web of the  
girder



**POOR.** Section loss up to 30% in critical area, fatigue or out-of-plane bending cracks may be present in primary members, previously arrested fatigue cracks propagating beyond arresting holes in primary members, fatigue cracks in secondary members throughout the bridge, anchor bolts or pintles broken on rocker bearings with an offset of  $\frac{1}{2}$ " or more between the rocker and the bearing or sole plates.

I-35

3/7/2024

35

## Item 59 - Steel Superstructures

### Poor Condition

- 25% section loss in web
- Hole at cope



**POOR.** Section loss up to 30% in critical area, fatigue or out-of-plane bending cracks may be present in primary members, previously arrested fatigue cracks propagating beyond arresting holes in primary members, fatigue cracks in secondary members throughout the bridge, anchor bolts or pintles broken on rocker bearings with an offset of  $\frac{1}{2}$ " or more between the rocker and the bearing or sole plates.

I-36

3/7/2024

36

## Item 59 - Steel Superstructures

### Poor Condition

- Cracked intermittent welds along edge of cover plate
- (cover plate area = 28% of bottom flange)



POOR. **Section loss** up to 30% in critical area, fatigue or out-of-plane bending cracks may be present in primary members, previously arrested fatigue cracks propagating beyond arresting holes in primary members, fatigue cracks in secondary members throughout the bridge, anchor bolts or pintles broken on rocker bearings with an offset of  $\frac{1}{2}$ " or more between the rocker and the bearing or sole plates.

I-37

3/7/2024

37

## Item 59 - Steel Superstructures

### Serious Condition

- Cracks in web along bottom flange
- Arrested crack perpendicular to stress in web
- 15% section loss in lower portion of web



SERIOUS. Advanced **section loss** up to 50%, extensive perpendicular to stress fatigue or out of plane bending **cracks** in primary members.

I-38

3/7/2024

38

## Item 59 - Steel Superstructures

### Critical Condition

- 80% section loss above bearing
- Critical section for bearing at beam end is cut horizontally
- Critical section for shear near beam end is cut vertically



**CRITICAL.** Severe **section loss** over 50% requires special inspections, temporary supports or repairs may be required to remain open to traffic. The Bureau of Bridges and Structures shall be notified immediately. (**install wood blocking**)

I-39

3/7/2024

39

## Item 59 - Steel Superstructures

### Critical Condition

- 50% section loss of web at mid-span
- 100% section loss of bottom flange at mid-span (completely disconnected from web)



**CRITICAL.** Severe **section loss** over 50% requires special inspections, temporary supports or repairs may be required to remain open to traffic. The Bureau of Bridges and Structures shall be notified immediately.

I-40

3/7/2024

40



## Item 59 - Steel Superstructures

### Critical Condition

Bottom flange cracked at bearing



**CRITICAL.** Severe **section loss** over 50% requires special inspections, temporary supports or repairs may be required to remain open to traffic. The Bureau of Bridges and Structures shall be notified immediately.

I-41

3/7/2024

41

## Item 59 - Steel Superstructures

### Critical Condition

- ❑ Severe section loss throughout
- ❑ 100% section loss above bearing
- ❑ Beam supported by bottom flange in flexure



**CRITICAL.** Severe **section loss** over 50% requires special inspections, temporary supports or repairs may be required to remain open to traffic. The Bureau of Bridges and Structures shall be notified immediately. (**install wood blocking**)

I-42

3/7/2024

42

## FATIGUE, FRACTURE & GUSSET PLATES

3/7/2024

IL NBI Refresher Course 2024

1

### Fatigue, Fracture & Gusset Plates

#### **Fatigue:**

The tendency of a member to fail at a stress level below yield stress when subjected to cyclical loading.

#### **Fracture:**

The separation of a member into two parts.



Fractured Girder

3/7/2024

I-2

2



## Fatigue, Fracture & Gusset Plates

### Fracture Critical Member (FC) **or** Nonredundant Steel Tension Member (NSTM):

1. **Must be steel**
2. **Must be in tension or have a tension component**
3. **Failure would likely cause partial or complete collapse of the structure**

I-3

3/7/2024

3

## Fatigue, Fracture & Gusset Plates

### Redundancy:

- **The structural condition where the number of supporting elements is greater than necessary for stability (alternate load paths exist)**
- **3-Types of Structural Redundancy**
  - **Internal**
  - **Structural**
  - **Load Path**


I-4

3/7/2024

4

## Fatigue, Fracture & Gusset Plates

**Internal Redundancy** – a member configuration containing 3 or more elements mechanically fastened together (by rivets or bolts) to form multiple independent load paths







3/7/2024

I-5

5

## Fatigue, Fracture & Gusset Plates

### Internal Redundancy



Riveted/Bolted Girder  
Has internal redundancy

Welded Girder  
No internal redundancy

3/7/2024

I-6

6

## Fatigue, Fracture & Gusset Plates

**Structural Redundancy** – provides continuity of load path from span to span on interior spans of continuous structures



I-7

3/7/2024

7

## Fatigue, Fracture & Gusset Plates

**Load Path Redundancy** – having 3 or more main load carrying members between substructure units

Load Path Redundant



Not Load Path Redundant



I-8

3/7/2024

8

## Fatigue, Fracture & Gusset Plates

### Non-Redundant Structures:

- **Do not have load path redundancy**
- Internal redundancy is disregarded
- Structural redundancy is disregarded

3/7/2024

I-9

9

## Fatigue, Fracture & Gusset Plates

### FC/NSTM INSPECTION PROCEDURES:

- Inspector background
- Equipment needs
- Where to look
- What to look for
- Nondestructive testing



3/7/2024

I-10

10

## Fatigue, Fracture & Gusset Plates

### INSPECTOR BACKGROUND:

(*preferred qualifications*)

- Experienced steel inspector
- Has taken the NHI course on Fracture Critical Inspection Techniques for Steel Bridges (**required** as of 1/1/2024 for all TL/PM on FC/NSTM structures)
- Has an understanding of structural behavior and fatigue prone details
- Attention to detail
- Willingness to access hard to reach locations



I-11

3/7/2024

11

## Fatigue, Fracture & Gusset Plates

Equipment Needs (Access Equip. – **Arms Length Reach**):



I-12

3/7/2024

12

## Fatigue, Fracture & Gusset Plates

### Equipment Needs (Damage Measurement):

- Tape measure
- Crack gauge
- UT thickness meter
- Hammer
- Wire brush
- Grinding wheel bit



I-13

3/7/2024

13

## Fatigue, Fracture & Gusset Plates

### Where to Look: (we will discuss each in detail)

- Areas vulnerable to corrosion
- Field, intersecting, plug (weld filled holes) & tack welds
- Sudden changes in cross section
- Stress risers (included in many of these)
- Locations with high displacement induced stress's
- Web stiffeners
- Coped sections
- Eyebars
- Pin and hanger assemblies

I-14

3/7/2024

14



## Fatigue, Fracture & Gusset Plates

### Where to Look - Areas Vulnerable to Corrosion:

#### *Locations that trap and hold moisture & debris*

- Beneath deck joints
- Near drains
- On flat surfaces
- Exposed surfaces of fascia beams
- Steel in contact with concrete
- At overlapping steel plates
- Corners on steel members

***Loss of section due to corrosion causes a stress riser that may be susceptible to fatigue***

I-15

3/7/2024

15

## Fatigue, Fracture & Gusset Plates

### Where to Look – Field, Intersecting, plug(weld filled holes) & Tack Welds

- Field & intersecting welds are more susceptible to flaws
- Flawed welds cause increased strain
- Fatigue cracks can initiate more easily at these locations
- Field, intersecting, tack and plug welds
- Any weld in a tension zone on a FCM that is not part of the original design should be documented and inspected



I-16

3/7/2024

16

## Fatigue, Fracture & Gusset Plates

### Where to Look – Sudden Change in Cross Section:

- Sudden changes in cross section cause stress increases
  - Cover plate terminations
  - Changes in plate size
- These are susceptible locations for fatigue cracks to initiate





I-17

3/7/2024

17

## Fatigue, Fracture & Gusset Plates

### Where to Look – Transverse Web Stiffeners/Cross Frames



- Stiffener is full height of web
- Ample corner clips
- Welded to web & Flanges
- Welds do not touch

**WELD LIMITS AND CLIP DETAILS**  
 \*\* Stop welds 1/2" (±1/8") from edges as shown. Typical.

**GOOD** Diaphragm connection details to WF girders



I-18

3/7/2024

18

## Fatigue, Fracture & Gusset Plates

### Where to Look – Transverse Web Stiffeners/Cross Frames



**WELD LIMITS AND CLIP DETAILS**  
 \*\* Stop welds 1/2" (±1/8") from edges as shown. Typical.

- Stiffener is full height of web
- Ample corner clips
- Welded to web & Flanges
- Welds do not touch
- Lateral Brace conn is bolted

**GOOD** Cross Frame connection details to PL girders


I-19

3/7/2024

19

## Fatigue, Fracture & Gusset Plates

### Where to Look – Transverse Web Stiffeners/Cross Frames



**POOR** Cross Frame connection details to girders

I-20

3/7/2024

20

## Fatigue, Fracture & Gusset Plates

### Where to Look – Cross Frames



**POOR** Cross Frame connection details – look at ends of plates in tension zones of girders

I-21

3/7/2024

21

## Fatigue, Fracture & Gusset Plates

### Where to Look – Transverse Web Stiffeners/Cross Frames



**POOR** Web Stiffener connection details – look at ends of plates in tension zones of girders


I-22

3/7/2024

22

### Fatigue, Fracture & Gusset Plates

#### Where to Look – Cross Frames & Diaphragms



Base of Connection PL not welded to Flange - **CRACKS**

Connection PL has too small of clip- welds too close - **CRACKS**

**POOR** Cross Frame/Diaphragm connection details – cracks at ends of PL in tension zones


I-23

3/7/2024

23

### Fatigue, Fracture & Gusset Plates

#### Where to Look – Cross Frames & Diaphragms



Crk thru web  
11/9/21  
2 1/4"

Check bk side of Web – Cracks can propagate thru

**POOR** Cross Frame/Diaphragm connection PL details – cracks at ends of PL in tension zones

I-24

3/7/2024

24



## Fatigue, Fracture & Gusset Plates

### Where to Look – Cross Frames & Diaphragms

Check bk side of Web – Cracks can propagate thru

**POOR** Cross Frame/Diaphragm connection PL details – cracks at ends of PL in tension zones

I-25

3/7/2024

25

## Fatigue, Fracture & Gusset Plates

### Fatigue Prone Details

#### Highly-Restrained Connections

“Hoan” like details

- ❑ Intersecting welds at stiffeners and connection plates without corner clips
- ❑ Transverse members rigidly connected to girder webs without attachment to flanges

I-26


3/7/2024

26



## Fatigue, Fracture & Gusset Plates

### Where to Look – Longitudinal Web Stiffeners:



I-27

3/7/2024

27

## Fatigue, Fracture & Gusset Plates

### Where to Look – Eyebars:



I-28

3/7/2024

28

## Fatigue, Fracture & Gusset Plates

### Recent Case: I-40 over Mississippi R. at Memphis

- May 2021, fracture of lower truss cord discovered during inspection
- Interstate closed due to severity
- Crack may have been present for a few years!
- Inspector from previous inspection cycles fired. Claimed it was a difficult to reach location.



I-29


3/7/2024

29

## Fatigue, Fracture & Gusset Plates

### What to Look For:

- Section Loss
- Poor Weld Details
- Crack Identification
- Evaluating the Crack



I-30

3/7/2024

30

## Fatigue, Fracture & Gusset Plates

### Nondestructive Testing Methods:

- **Ultrasonic Testing** – Method uses high frequency sound waves to measure material thickness. Surface must be relatively smooth and clean. Effective in finding surface & subsurface defects.
- **Magnetic Particle Test** – Method uses a magnetic field with iron particles to locate defects. Can be difficult to use in the field. Effective in finding surface & subsurface defects.
- **Dye Penetrant Test** – Method involves applying an oil based liquid penetrant & a developer around a suspected crack. Surface must be very clean. Effective in finding cracks open to the surface

I-31

3/7/2024

31

## Fatigue, Fracture & Gusset Plates

### GUSSET PLATE INSPECTION:

- **Background**
- **Inspection Procedures**
- **General Findings**



I-32

3/7/2024

32

## Fatigue, Fracture & Gusset Plates

### BACKGROUND: I-35W over Mississippi R. Collapse

- August 1, 2007 failure of 14 span deck truss
- Loss of 13 motorists lives
- February 2009, FHWA Pub. No. FHWA-IF-09-014: Load Rating Guidance and Examples for Bolted and Riveted Gusset Plates in Truss Bridges
- January 29, 2010, FHWA Tech Advisory 5140.31: Inspection of Gusset Plates using Non-Destructive Evaluation
- May 11, 2010, IDOT ABD Memo 10.2: Load Rating Guidance for Bolted and Riveted Gusset Plate in Steel Truss Bridges
- 2010 – IDOT Local Roads CL 2010-09 recommends Gusset Plate inspections & ratings for all qualifying bridges
- October 2015, IDOT ABD Memo 15.5: Revised Load Rating Guidance for Gusset Plates



I-33

3/7/2024

33

## Fatigue, Fracture & Gusset Plates

### BACKGROUND: GP Locations & Numbers



840 Gusset Plates

596 Gusset Plates



I-34


3/7/2024

34

## Fatigue, Fracture & Gusset Plates

### GP INSPECTION PROCEDURES

- Arms length access to FC-GP
- Equipment needs:
  - Appropriate access equipment
  - Measurement tools
- Key Indicators:
  - Section Loss
  - Cracks
  - Plate Distortions
  - Damaged Fasteners



I-35


3/7/2024

35

## Fatigue, Fracture & Gusset Plates

### GENERAL FINDINGS: Gusset Plate Condition

- Condition varies depending on location
- Age & maintenance history important factors
- Locations above “splash line” generally good
- Locations below the splash line more susceptible
- Areas at PL or member connections more susceptible



I-36

3/7/2024

36

## Fatigue, Fracture & Gusset Plates

### Field Photos: GP in good condition



3/7/2024

I-37

37

## Fatigue, Fracture & Gusset Plates

### Field Photos:



3/7/2024


I-38

38



## Fatigue, Fracture & Gusset Plates

### Field Photos:



I-39

39

## Fatigue, Fracture & Gusset Plates

### Field Photos:



I-40

40

## Fatigue, Fracture & Gusset Plates

### Field Photos: Poor repairs



3/7/2024

I-41